# IECEx CoC
# Certified Service Facility

## INTERNATIONAL ELECTROTECHNICAL COMMISSION
### IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: **IECEx SIM S0003**

Page 1 of 1

Certificate history:

Status: **Current**

Issue No: 3

Issue 3 (2022-08-02)
Issue 2 (2014-01-03)
Issue 1 (2011-10-11)
Issue 0 (2010-06-02)

Date of Issue: 2022-08-02

Applicant: **JATCO (Australia) Pty Ltd t/a Applied Resolution Technologies**
Lot 521 Sullivans Road
Yamba NSW 2464
**Australia**

Type of Service: **Repair, overhaul& reclamation to IEC 60079-19:2019**

Type of Protection: **Intrinsic Safety "i"**

Scope of Service: Repair and Overhaul of Intrinsically Safe Alignment Lasers

Locations covered by this Certificate:

**JATCO (Australia) Pty Ltd**
Lot 521 Sullivans Road
Yamba NSW 2464
Australia

Facility Audit Report:

AU/SIM/FAR10.0001/12

*This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.*

Approved for issue on behalf of the IECEx Certification Body: **Geoffrey Barnier**

Position: **Principal Engineer - Certification**

Signature:
(for printed version)

Date:
(for printed version) 2 August 2022

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.

Certificate issued by:

**Safety in Mines Testing and Research Station (Simtars)**
**2 Robert Smith Street**
**REDBANK QLD 4301**
**Australia**